TECHNICAL DATASHEET STONE OIL (STENOLJA)

Selder & Company AB 23.3.2021 www.selder.com/en

Drying oil which protects ceramic, tiles, concrete and other porous stone against dirt and wet. Contains no solvents.



STONE OIL is linseed oil from which the nondrying ingredients have been removed with our unique refining method. It penetrates the substrate and dries quickly by a reaction with the oxygen in the air to linoxyn, a natural polymer with excellent adhesion. It is non-biodegradable, waterrepellent and resistant to fats, petroleum products, salts and household acids.

Work manual

Visit our website at <u>www.selder.com/en</u> and follow its detailed instructions.

Instructions - summary

Test the final tone: The treated surface usually gets the same tone as when wet. Test by wiping the surface with water.

Test white ceramic. In some cases, white ceramic takes on a yellowish tint, which isn't visible when wet with water. Before treating white ceramic, test by applying STONE OIL to a small area.

Clean: Stains of dirt must first be removed

as the treatment otherwise makes them permanent.

Impregnate: Apply liberally with a brush. **Floors in public spaces subject to dirt:** Heat STONE OIL to 130 °C in a deep fryer. Apply liberally with a natural bristle brush.

Futher measures: Spread oil from places that are saturated to places that still absorb oil. Apply and spread until the entire surface is saturated.

Wipe off excess oil: After 20-30 minutes, thoroughly wipe off any oil remaining on the surface. Oil remaining on the surface forms a sticky skin.

Allow time to oxidize for at least 24 hours. Polish with some STONE OIL and a red pad on an even surface, and a brown pad on a coarse surface. Keep the surface moist by adding STONE OIL to the pad. Continue until the entire surface has an even gloss. Wipe dry: Remove any residue of oil and polishing dust by wiping the surface thoroughly with a dry cotton cloth. Wash brushes, tools and utensils with strong soft soap.

Worker protection: Respiratory protection is not required. Provide good ventilation, especially when working with oil at 130 °C. The oil conducts little heat and at this temperature does not cause burns in the event of spillage.

Contains: Drying (oxidizing) fatty acids of linseed oil.

Dry matter: 100 %

Drying time: Less than 24 hours at 20 °C and good ventilation.

Consumption: 1-2 dl/m².

Packaging: 1 and 5 litre cans, 200 litre drums, 1000 litre IBC containers.

Safety: Consists of oxidizing fatty acids that **can ignite spontaneously**. Cloths, shavings and other porous materials that have been moistened with STONE OIL must be immersed in water without delay.

Unfit for consumption: Dries in the digestive tract and causes diarrhea.

Metal objects burn when lifted from hot oil.

Selder & Company AB Knivstagatan 11 75323 Uppsala, Sweden atle@selder.com +46 73 0700 384

